


Take the following measurements while patient is weight bearing.


1 Foot circumferences

- a Mark the measuring points
- b Measure the circumference




2 Foot lengths

- a Measure the length on the medial and lateral of the foot
- b Measure the distance from A1 to the base of the toe 1 & 5.



3 Toe circumferences

- a Mark the measuring points
- b Measure circumference cX at web area
- c Measure circumference cZ at the desired termination point



4 Toe lengths

- a Measure length from web to desired termination point

